



SV 18 R


S 4 2529 N








N 88 45


S3 664 N






















	1	16	10	10	20	21	22	23	24	26	26	1/1	60
1	\Rightarrow	8 .	9	9.5	0	105	11	11,5	12	13	14	1/2	ñ
	S-MODU	4	45	4.75	5	5,25	5.5	5.75	6	6.5	7	1/4	ď
	둦	2	2,25		2.5		2.75		,3	3,25	3.5	1/1	-
	7	1			1,25				1.5		1,75	1/2	~
	וע	0,5							0.75		1	1/4	DI
197	Q.	0.25							100000000			1/8	0
1	(BAN)	1/2	9/16	19/32	5/8	21/32	11/16	23/32	3/4	13/15	7/8	1/1	00
10	4 9	1	11/8	1 2/16	The same of the sa	1 5/16	13/8	17/16	1 1/2	15/8	13/4	1/2	00
0	~	5	21/4	23/8	21/2	25/8	2 3/4		3	31/4	3 1/2	1/4	4
a 2	1	4	41/2	4 3/4	5	51/4			6	6 1/2	7	1/1	7
-	D	8	9	9 1/2		10 1/2		11 1/2		13	14	1/2	-
b=6	8	16	18	19	20	21	22	23	24	26	28	1/4	DΙ
75.5	ч	32	36	38	40	42	44	46	48	52	56	1/8	q
d 2		32	36	38	40	42	44	46	40	52	56	1/1	40
a c	=	16	18	19	20	21	22	23	24	26	28	1/2	D
	E	8	9	9,5	10	10,5	11	11.5	12	13	14	1/4	1
	11	4	4,5	4.75	5	5,25	5,5	5,75	6	6.5	7	1/1	~
	D	2	2,25		2.5		2.75		3	325	3,5	1/2	
	1	1			1,25			and S	1,5		1.75	1/4	P
1	- 7	0,5		-			_		0,75			1/8	q
	1	0,7	962	0,59	0,56	0,53	0,51	0.49	0,47	043	0,4	1/1	1
4	1	0,35	0,31	0.204	0,29	0.266	0,254	0.243	0,235	0,215	0,2	1/2	~
	F	0,175	0,155	0.447	0,14	0,133	0,127	0,122	0,117	0.008	0.1	1/4	N I
1	E	9088	0.078	0,0%	007	0.067	0,064	0.061	0.058	0.054	0,05	1/8.	<u>-</u>
	1	40	0	0	7	R		L	9	9	4		M
								GENERAL II				_	ы.

SVIBR

S4 2532N

0	-	1	2	3	4	5	6	7	8	9	10	-0	
4	1/8	0,35		0,3			-	0,25			0,2	_	-
P	11/4	0,7	0,65	0.8		0,55		0,5		945	0,4		1
-	1/2	1,4	1,3	1,2	1,15	1,1	1,05	1	0,95	0,0	9,8	d 60	1
-	1/1	2,8	2,6	2,4	2,3	2,2	2,1	2	1.9	1,8	1,6	D-40	
•	1/4	5,6	5,2	4,8	4.6	4,4	4.2	4	3,8	3,6	3,2	h-48	1
b	1/2	11.2	10,4	9.6	9.2	8.8	8,4	8	76	7,2	6,4	a 24	
20	1/1	22,4	20,8	19,2	18.4	17.6	18.8	16	15,2	14.4	12,8		1
•	1/8		7-3	5,15	-		July 1	2			12.	V-2-7-5	
D	1/4	919	- 2	0,75				1			95	DATE MARK	#1:52
7	1/2	1,75	0,20	1,5		-,.0		1,25		-,	1	d 48	
-	1/1	3,5	3,25	3	0,110	2,75	0120	2,5	17,70	2,25	2	b-60	1
P	1/4	7	6,5	6	5,75	5,5	5,25	5	4,75	4,5	4	a 24	1
9	1/2	14		12	11,5	11	10,5	10	9,5	g	8	0 2/	1
	1/1	28	26	24	23	22	21	20	19	18	16		1
1	1/4	1,75		4.5				1,20			0.5		P
D	parties and	3,5	3,23	- 2700		2,10		1,25		2,20	1	~ ~ ~	
7	1/2		3,25	3	5.75	2,75	5,20	25	3,72	2,25	2	d 24	P
4	1/1	7	_	12	-	5.5	5,25	5	4,75	4.5	4	b-60	11
P	1/2	28	13	50-	11.5	H	10,5	10	9.5	9	8	<u>a</u> 24	2
0	1/1	56	52 26	4 8	23	22	21	20	19	18	16	- 0/	8
7	1/8	1.75		1.5	10	41	42	40	38	36	32	-	2
2	1/4	3,5	3,25	3		2,75		2,5	-	2,25	2		
	1/2	7	6,5	6	5,75	5,5	526	5	475	4,5	4	U 24	
T	1/1	14	13	12	11,5	11	10,5	10	9,5	0	8	d 24	
q	1/4	28	26	24	23	22	21	20	19	18	16	b-60	. 8
Ì	1/2	56	52	48	46	44	42	40	38	36	32	<u>a 48</u>	
S.	1/1	112	104	96	92	88	84	80	76	72	64		
4	1/8										1,25		
P	14			3,75							2,5		
	1/2	8,75		7.5				6,25			5	d 24	
-	1/1	17,5	16,25	15	4	13,75		12,5		11.25	10		
1	1/4	35	32,5	30	28,75	27,5	26,25	25	23,75	22,5	20	1 10	
	1/2	70	65	60	57,5	55	52,5	50	47,5	45	40	a 60	
	1/1	140	/30	120	115	NO	105	100	95	90	80	7.	

SV 18R S4 2533 N

(A)	-	1	2	3	4	5	6	7	8	9	10	-0	
4	1/8	140	130	120	115	110	105	100	95	90	80		1
8	1/4	70	65	60	57 1/2	55	52 1/2		47 1/2	45	40		
77	1/2		32 1/2		28 3/4	-	-	25	23 34	22 #2	20	d 60	
	1/1	17 1/2			K+ 3/8	7000 700	13 1/8	12 1/2	11 7/3	11 1/4	10	The Person of th	
1	1/4		1	7 1/2		6 7/8		6 1/4		5 5/8	-	b-48	
Ď	1/2	4 3/8		3 3/4				3 1/8			2 1/2	a 24	-
9	1/1	1	15.4	1 7/8				11000			1 1/4		1
4	1/8	112	104	96	92	88	84	80	76	92	64		
D	1/4	-	52	48	46	44	42	40	38	36	32	- 10	
7	1/2	28	26		11 1/2	22	21	20	19	18	16	d 48	
-	1/1	14	13	12	200	11	10 1/2	Ю	9 1/2	9	8	b=60	
8	1/4	7	6 1/2	6	5 3/4	5 1/2	5 1/4	5	4 3/4		4	0 24	
34	1/2		3 1/4	3	2 7/8	2 3/4	2 5/8	-	2 3/8	2 14	2	- 0/	
90	111	1 3/4	1 5/8	1 1/2	1 7/16	1 3/8	1 5/16	1 1/4	1 3/16	1 118	1		1
P	1/8	28	26	24	23 46	22	42	20	38	18 36	32	3 2	1
8	1/4	14	13	12	11 1/2	11	10 1/2	10	9 1/2	9	16	u 24	1
7	1/2	7	6 1/2	6	5 3/4	5 1/2	5 1/4	2853	0 110	23.	8	d 24	1
	1/4	3 1/2	3 1/4	3	2 9/8	2 3/4	2 5/8	2 1/2	2 3/8	2 1/4	2	b=60	1
8	1/2	1 3/4	1 5/8	1 1/2	1 7/16	1 3/8	-		-		1	0 24	5
4	1/1	7/8	13/16	3/4	23/32	11/16	1 5/16	5/8	19/32	9/16	1/2	CHECK SAME	
	1/8	28	26	24	23	22	21	20	19	18	16		
8	1/4	14	/3	12	11 12	11	10 1/2	10	9 1/2	9	8		
-	1/2	7	6 1/2	6	5 3/4	5 1/2	5 1/4	5	4 3/4	4 1/2	4	d 24	
7	1/1	3 1/2	3 1/4	3	2 7/8	2 3/4	2 5/8	2 1/2	2 3/8	2 14	2		
_	1/4	1 1/4	1 5/8	1 1/2	1 7/16	1 3/8	1 5/15	1 14	1 3/16	1 1/8	1	b-60	
8	1/2	7/8	13/16	3/4	23/32	11/16	21/32	5/8	19/32	9/16	//2	a 48	
80	1/1	7/16	13/32	3/8	23/64	-	21/64	5/16	19/64	9/32	1/4	(
SOM:	1/8	22 2/5	20 4/5	19 1/5	IB 2/5	17 3/5	16 4/5	16	15 1/5	# 2/5	12 4/5	4	
8	1/4	11 1/5	10 2/5	9 3/5	9 1/5	8 4/5	8 2/5	8	7 3/5	7 1/5	6 2/5	26, 7	
-	1/2	5 3/5	5 1/5	4 4/5	4 3/5	4 2/5	4 115	4	3 4/5	3 3/5	3 1/5	d 24	
7	1/1	2 4/5	2 3/5	2 2/5	2 3/10	2 1/5	2 1/10	2-	19/10	14/5	1 3/5	b=48	
4	1/4	1 2/5	1 3/10	1 1/5	1 3/20	1 1/10	1 1/20	1	19/20	9/10	415	<u>a</u> 60	
b	1/2	7/10	13/20	3/5	23/40	11/20	21/40	1/2	19/40	9/20	2/5		103
90	1/1	7/20	13/40	3/10	23/80	11/40	21/80	1/4	19/190	9,40	115		

54

2534 N

(4)	-	1	2	3	4	5	6	7	8	9	10	- 0	L
4	1/8							-					
P	114	0,35	0,00	0,3	-77	0.75		0,25		21.77	0,2		
7	1/2	0,7	0,65	0,6	111.5	0.55	100	0,5	5,55	0,45	0,4	d 60	
	1/1	1,4	1,3	1.2	1,15	1,1	1,05	1	0,05	49	98	b-48	
8	114	2,8	2.6	2.4	2,3	2,2	2.1	2	1,9	4.8	1,6	<u>a</u> 24	
9	1/2	-					-	4			-	0 2/	
-	1/1	===						8				7.0	1
₫ .	1/4	-						-	22	71.00	0.25		
D	1/2		-	0.75							0,5	d 48	1
7	1/1	1,75	_	1,5	_			1,25					
9	1/4	3,5	3,25	3	211	2,75		2,5	-	2,25	2	b-60	
Þ	1/2	7	6,5	6	5.75	6,5	5.25	5	4.75	4,5	4	a 24	
	1/1	14	13	12	11,5	11	1425	10	9,5	9	8	A-0	
-	1/6										0,25		
8	1/4			0,75							0,5	98	U
h	1/2	1,75		1,5				1,25			1	d 24	L
7	1/1	3,5	3,25	3		2,75		2.5		2,25	2	b-60	
1	1/4	7	6.5	6	5.75	5,5	5,25	5	4.75	4.5	4		_
D	1/2	14	13	12	11.5	#	10.6	10	9,5	g	в	0 24	Z
0	1/1	28	26	24	23	22	21	20	19	18	16		-
ų	1/8			Q75							0,5		e
P	1/4	1.75		1,5			0	425			1		
	1/2	3,5	3,25	3		2,75		2,5		2,25	2	d 24	
4	1/1	9	6,5	6	5.75	5,5	5,25	5	4,75	4,5	4	b-60	
1	1/4	14	13	12	11.5	#	10,5	10	2,5	9	В	<u>a 48</u>	
Š	1/2	20	29	24	23	22	21	20	19	18	16	0 /9	4
20	1/1	56	52	48	46	44	42	40	38	36	32		
4	1/8					-4-							
8	1/4			3,75							1,25	d 24	
7	1/2	8,75	-			17-11-		0,20		-	2,5		
y _	1/1	f7.5		7.6		1J.YD	-	6,25	-	77,23	5	0 60 b-48	
P	1/2	35	32,5	30		13.75		25	-	22,5 H,25	20	0 60	
	1/1	70	65	60	57,5	55 23,5	52,5	50	425	45	40	32 /	

SV IBR

S4 2535 N

A.	-	1	2	3	4	5	6	7	8	9	10		
1	18	224	208	192	184	176	168	160	152	144	128	-	
D	1/4	- 112	104	96	92	88	84	80	765	72	64	d-48	
7	1/2	56	52	48	46	44	42	40	38	36	32	c_60	
	1/9	28	26	24	23	22	21	20	19	18	16	0 113	
4	1/4	14	13	12	11 1/2	- 11	10 1/2	10	9 1/2	9	8	0 = 113	
Ď	1/2	7	6 1/2	6	5 3/4	5 1/2	5 1/4	5	4 3/4	4 1/2	4		
40	1/1	3 1/2	3 1/4	3	2 7/8	2 3/4	2 5/8	2 1/2	2 3/8	2 1/4	2		11
1	1/8	140	130	120	115	110	105	100	95	90	80		
b	1/4	70	65	60	57 1/2	55	52 1/2	50	47 1/2	45	40	d 24	
1	1/2	35	32 1/2	30	28 3/4	27 //2	26 1/4	25	23 3/4	22 1/2	20	c 48	ľ
	1/1	17 1/2	15 1/4	15	14 3/8	13 3/4	13 1/8	12 1/2	11 7/8	11 14	10	10 113	1
ď	1/4	8 3/4	8 1/8	2 1/2		6 1/8		6 1/4		5 5/8	5	6 113	١
Ď	1/2	4 3/8		3 3/4				3 1/8	- 1		2 1/2	- 90	L
8	1/1	8 - V = V		1 7/8		(c. =)					1 1/4		1
9	1/8	112	104	96	92	88	84	80	96	72	64	1	1
D	1/4	56	52	48	46	44	42	40	38	36	32	d 24	ŀ
>	1/2	28	26	24	23	22	21	20	19	18	16	c_60	l
	1/4	14	- 13	12	11 1/2	11	10 1/2	10	9 1/2	g	8	1	L
ď	1/4	7	6 1/2	6	5 34	5 1/2	5 1/4	5	4 3/4	4 1/2	4	B = 113	ı
Ď	1/2	3 1/2	3 1/4	3	2 7/8	2 3/4	2 5/8	2 1/2	2 3/8	21/4	2	24	ı
90	1/1	1 3/4	1 5/8	1 1/2	1 7/16	1 3/8	1 5/16	1 1/4	1 3/16	1 1/8	1		Г


SV IBR


S4 2536 N


	⊗	-	1	2	3	4	5	6	7	8	9	10	- -⊗
	4	1/8	0,02	0,022	0,023	0,024	0,025	0,027	0,028	0,029	0,031	0,035	
	I.P	1/4	0,04	0,043	0.047	0,049	0,051	0,053	9056	9059	0,062	907	
	14	1/2	0,08	4.086	0,093	0,097	4102	0,107	9112	0,118	0,124	0,14	d 60
		1/1	0,16	0,172	0,186	0195	0,203	9 2/3	0,294	0,236	0,248	0,28	5-48
nar 155 /min	1	1/4	0,32	0,345	937	0,39	0,405	4425	0,45	0,47	2,5	0,56	Q 24
	Ŝ	1/2	0,64	0,68	0,74	0,78	981	485	49	495	1	1,12	
A C	8	1/1	1,28	1,38	148	1,56	4,62	670	1,80	1,90	2	2,24	1 10
	Q	1/8	0,025	0.027	4029	0,03	0,032	0,033	0,035	0,037	0,039	0.044	1
	8	1/4	0,05	0,054	0,058	0,061	0,064	0,067	0,07	9074	0,048	0,088	
	7	1/2	6.1	0,108	0,117	0,122	9 127	0,/33	0,14	0, 147	0,155		d 48
		1/1	0,2	0,215	0,233	0,243	9,254	0,266	0,28	0,294	0,31	0,35	6-60
nai. 155/min	d	1/4	0,4	0,43	0,47	0,49	0,51	0,53	466	0,59	962	0.9	a . 24
C C	Ď	1/2	0,8	0,86	0.94	0,98	1,02	1,06	1,12	1,18	1,24	14	3.
100	80	1/1	1,6	472	488	1.96	904	2,12	2,24	2,36	2,48	2,8	
	8	118	0,05	0,054	0,058	0,061	9.064	0.067	407	0,094	0.098	0,088	
	h	14	0,1	0,108	0,117	0,122	9 127	0,133	9/4	9147	0,155	0,195	
	2	1/2	0,2	0,215	9233	0,243	0,264	0,266	088	9294	0,31	0,35	a 24 b - 60 d 24
1000		1/1	0,4	0,43	947	0,49	0,51	0,53	456	0,59	0,62	0,9	2 24
nov. 355 /min	lď	14	0,8	0,86	0,94	0.98	4,02	1.08	1,18	449	424	1,4	
C C	Ď	1/2	1,6	1,72	1,88	196	2,04	2,12	2,24	2,36	2,48	2,8	
AAA	80	1/1	3,2	3,44	3,78	3,92	4.1	4,24	4,48	4,72	4,96	5,6	-
900 /min.	8	1/8	0,1	0,108	0,117	4122	4127	0,133	0,14	947	0,155	0,175	d 24
mar	5240	1/4	0,2	0,215	0,233	9243	0,254	0,866	0.28	4294	0,31	0,35	9 48 6 - 80 7 24
(O	1	1/2	0,4	0,86	0,47	0,49	0,51	0,53	0,56	459	0.68	0,9	9 48
C	4	1/1	0,125	0,134	0,46	0,152	1,02	1,07	1,12	1,18	1,24	1,4	
78.0	8	1/4	0,25	0,27	0,29	0,304	0,32	0,167	0,35	1,184	0,39	0,22	d 24
	0.75	1/2	0,5	0,54	0,58	0,61	0,64	0,57	0,9	0,74	978	0,44	9 60 0 24
	1	1/1	1	4,08	4/7	1,22	427	4,33	44	1,47	4,55	175	a 60


S4 2537 N


EV IBR
















SV 18 R

54 3003 N





SV 18R.

S3 1039 W

N